

### **3745-68-73 General operating requirements.**

Before adding hazardous waste, the owner or operator shall bring his thermal treatment process to steady state (normal) conditions of operation- including steady state operating temperature- using auxiliary fuel or other means, unless the process is a non-continuous (batch) thermal treatment process which requires a complete thermal cycle to treat a discrete quantity of hazardous waste.

Effective: 01/07/1983

119.032 review dates: Exempt

Promulgated under: 119.03

Statutory authority: 3734.12

Rule amplifies: 3734.12

Prior effective dates: 04/15/1981