

Upper Sandusky River Watershed TMDLs




Figure 2: Riparian condition scores of the Bucyrus assessment unit (04100011-020)




Figure 3: Riparian condition scores of the Broken Sword Creek assessment unit (04100011-030)

Upper Sandusky River Watershed TMDLs




Figure 4: Riparian condition scores of the Upper Sandusky assessment unit (04100011-040)

Upper Sandusky River Watershed TMDLs




Figure 6: Riparian condition scores of the Lower Tymochtee Creek assessment unit (04100011-060)

Upper Sandusky River Watershed TMDLs




Figure 7: Riparian condition scores of the Mexico assessment unit (04100011-070)




Figure 8: Riparian condition scores of the Honey Creek assessment unit (04100011-080)




Figure 9: Riparian condition scores of the Tiffin assessment unit (04100011-090)